

St. MARY'S CHURCH, MALTON
(formerly Malton Priory)
North Door, west face

Mortars and condition




Ordinary Portland Cement




Roman Cement



Lime-based mortar



Salt-related decay



0

2m